

Council District 7

# Hansen Dam Swim Lake

11798 Foothill Boulevard Lakeview Terrance 91342

Built: 1999 Capacity: 3375 people

April-October 2003: The pool served 28,532 patrons.

Median Household Income of the Area: \$35,236

Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Holiday
10AM TO	10AM TO	10AM TO	10AM TO	10AM TO	10AM TO	10AM TO	10AM-
7PM	7PM	7PM	7PM	7PM	7PM	7PM	7PM

#### Programs:

Facility Features:	YR ROUND POOL (OUTDOOR/ UNHEATED) PICNIC TABLES VOLLEYBALL COURT (UNLIGHTED)
Special Features:	2 WATER SLIDES BIRTHDAY PARTIES
Sports Programs:	
Other Programs:	BEACH VOLLEYBALL CANOEING FISHING JUNIOR LIFEGUARD PROGRAM KAYAK FITNESS PROGRAM KAYAKING MODEL BOATS PEDAL BOATS RECREATIONAL BOATING SAILING SWIM LESSONS WINDSURFING

Overall good condition. Pool supply lines have already been replaced.

На	Hansen Dam Pool – Immediate Repairs Needed						
1	Paint and caulk pool tank	\$85,000					
2	Paint interior and exterior of building	\$47,500					
3	Replace domestic water fill line	?					
ТС	DTAL	\$132,500					



## Council District 7 Hubert H. Humphrey Pool (YEAR ROUND POOL)



12560 Filmore Street Pacoima 91331

Built: 1970 Capacity: 279 people (90 in small pool)

Calendar 2003: The pool served 17,302 patrons.

Median Household Income of the Area: \$36,683

Facility Hours Of Operation: 2004

Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Holiday
12PM; 1PM 12 TO 5PM; TO	10AM TO 2PM; 1PM ) 5PM; 6PM TO 8PM	10AM TO 12PM; 1PM TO 5PM; 6PM TO 8PM	10AM TO 12PM; 1PM TO 5PM; 6PM TO 8PM	10AM TO 12PM; 1PM TO 5PM; 6PM TO 8PM	12PM TO 6PM	12PM TO 6PM	1PM- 5PM
Programs:							
Facility Features:	YR RO	UND POOL (OUT	DOOR/ HEATE	D)			
Special Features:	: WATEF	R SLIDE					
Sports Programs: NOVICE SYNCHRONIZED SWIM TEAM NOVICE WATER POLO TEAM NOVICE SWIM TEAM NOVICE SPRINGBOARD DIVING JUNIOR LIFEGUARD TRAINING SWIM LESSONS (ADULT/YOUTH/GROUP/PRIVATE/SEMI-PRIVATE) WATER EXERCISE							
Other Programs: LIFEGUARD TRAINING PROGRAM							

This pool received refurbishment by Recreation and Parks Facility Repair Division in 2002, for a total cost of \$481,000. Work included installing new pool lights in the large and small pools, replacing lifeguard towers, sealing joints, repainting the tank, and replacing the pool deck. Installation of a new pool heater and all related piping and utilities for the large pool is in progress. The bathhouse needs refurbishment and upgrade for ADA compliance.

Hu	Hubert Humphrey Pool – Immediate Repairs Still Needed					
1	Refurbish bathhouse: paint interior and exterior,	\$120,000????				
	plumbing fixtures, doors, floors, electrical, tile					
	and partitions.					
ТС	DTAL	\$120,000				

**Council District 8** 



Council District 7 **Ritchie Valens Pool** 10731 Laurel Canyon Boulevard

Pacoima 91331

Built: 1960 Capacity: 360 people

Summer of 2003: The pool served 10,559 patrons.

Median Household Income of the Area: \$36,557

Facility Hours Of Operation: 2004

Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Holiday
10AM TO	10AM TO	10AM TO	10AM TO	10AM TO	12PM TO	12PM	1PM-5PM
12PM; 1PM	12PM; 1PM	12PM; 1PM TO	12PM; 1PM	12PM;	6PM	TO 6PM	
TO 6PM	TO 6PM	6PM	TO 6PM	1PM TO			
				6PM			

#### **Programs:**

Facility Features:	SEASONAL POOL (OUTDOOR/ UNHEATED)
Sports Programs:	NOVICE INNER TUBE WATER POLO NOVICE SPRINGBOARD DIVING NOVICE SWIM TEAM NOVICE SYNCHRONIZED SWIMMING
Other Programs:	JUNIOR LIFEGUARD TRAINING PROGRAM SWIM LESSONS (PRIVATE,SEMI-PRIVATE,PARENT/CHILD)

Overall this pool is in fair condition. The deck and deck drains should be replaced, and minor repairs are needed in the bathhouse. Upgrades for ADA are needed.

Rit	Ritchie Valens Pool – Immediate Repairs Needed						
1	Paint and caulk pool tank	\$55,000					
2	Filter room lighting	\$3,500					
3	Replace concrete on surge pit top	\$15,000					
4	Replace deck and deck drains	\$215,000					
5	Ladders, anchors, lifeguard towers, diving board	\$20,000					
	stands, and other hardware						
6	Paint interior and exterior of building	\$47,500					
7	Replace partitions	\$55,000					
TC	DTAL	\$411,000					





Council District 7 Sepulveda Pool 8737 Kester Street Panorama City 91402

Built: 1959 Capacity: 360 people

Summer of 2003: The pool served 11,796 patrons.

Median Household Income of the Area: \$26,969

### Facility Hours Of Operation: 2004

Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Holiday
10AM TO 1PM; 2PM TO 6PM	10AM TO 1PM; 2PM TO 6PM	10AM TO 1PM; 2PM TO 6PM	10AM TO 1PM; 2PM TO 6PM	10AM TO 1PM; 2PM TO 6PM		12PM TO 6PM	1PM-5PM

#### Programs:

Facility Features:	SEASONAL POOL (OUTDOOR/ UNHEATED) WITH WATERSLIDE
Sports Programs:	NOVICE INNER TUBE WATER POLO NOVICE SWIM TEAM
	NOVICE SYNCHRONIZED SWIMMING
Other Programs:	JUNIOR LIFEGUARD TRAINING PROGRAM SWIM LESSONS (PRIVATE,SEMI-PRIVATE,PARENT/CHILD)

The building was refurbished in 2002 and is good shape. The pool needs a new electrical service panel in the filter room, and some work for ADA compliance is still needed.

Se	Sepulveda Pool – Immediate Repairs Needed						
1	Paint and caulk pool tank	\$55,000					
2	Replace electrical panel and controls in filter	\$15,000					
	room						
3	Paint interior and exterior of building	\$50,000					
ТС	DTAL	\$120,000					





Council District 7 Sylmar Pool 13109 Borden Avenue Sylmar 91342

Built: 1962 Capacity: 300 people

Summer of 2003: The pool served 8,569 patrons.

Median Household Income of the Area: \$51,176

Facility Hours Of Operation: 2004									
Monday	Tuesday	Wednesday	Thursday	Friday	Saturday	Sunday	Holiday		
10AM TO 1PM; 2PM TO 6PM	10AM TO 1PM; 2PM TO 6PM	10AM TO 1PM; 2PM TO 6PM	10AM TO 1PM; 2PM TO 6PM	10AM TO 1PM; 2PM TO 6PM		12PM TO 6PM	1PM-5PM		

#### Programs:

Facility Features:	SEASONAL POOL (OUTDOOR/ UNHEATED)
Sports Programs:	NOVICE INNER TUBE WATER POLO NOVICE SPRINGBOARD DIVING NOVICE SWIM TEAM NOVICE SYNCHRONIZED SWIMMING
Other Programs:	JUNIOR LIFEGUARD TRAINING PROGRAM SWIM LESSONS (PRIVATE,SEMI-PRIVATE,PARENT/CHILD)

The pool building needs refurbishment and upgrades for ADA compliance. A new pool and pool equipment is recommended because pool structure is tilting, which causes cracks and piping problems.

